(EAS					
de y	taw [	cht I	cois	Windo	₩ Help
احمات	0/4	e la	desig	2 takti	4
-				12.11.	

	:::
<sup>17</sup> Drafts	27.4
<sup>⊝</sup> Pending	-
Active	
™ L1: (50) ("5601463"	2
🗆 🍟 L2: (5702) outboard adj mot	C
<sup>™</sup> L3: (364146) nozzle or jet	-
	200
<sup>15</sup> L5: (350) 2 same 3 <sup>15</sup> L6: (51) 4 same 5	200
L6: (51) 4 same 5	222
₹ L7: (378) fell.in.	2000
💆 L8: (1672) ohara.in.	200000
Fa: (100) (***0/20).CCF2.	000000
™ L10: (266) (440/42).CCLS.	200000
💆 L11: (0) ("tiller").PN.	0000
<sup>™</sup> L12: (7059) tiller	-
🍮 L13: (786758) cable	000000
<sup>52</sup> L14: (61) 3 same 12	Second
Failed	
d count	3

	Type	L #	Hits	Search Text	DBs	Time Sta Comme Error	Definiti Er
ı	BRS	L1	50	("5601463"	USP	2004/09/2	0
2	BRS	L2	5702	outboard adj motor	USP	2004/09/2	0
	BRS	L3	3641	nozzie or jet	USP	2004/09/2	0
	BRS	L4	9362	steering	USP	2004/09/2	0
5	BRS	L5	350	2 same 3	USP	2004/09/2	0
3	BRS	L6	51	4 same 5	USP	2004/09/2	0
7	BRS	L7	378	fell.in.	USP	2004/09/2	0
3	BRS	L8	1672	ohara.in.	USP	2004/09/2	0
)	IS&R	L9	766	(440/38).CCLS.			0
10	IS&R	L10	266	(440/42).CCLS.	USP	2004/09/2	0
11	IS&R	L11	0	("tiller").PN.	ÜSP	2004/09/2	0
12	BRS	L12	7059	tiller	ÛSP	2004/09/2	0

NUM